



ENVIRONMENTAL COMPLAINTS & LOCAL SERVICES  
TOTAL RETENTION FACILITIES  
TOTAL RETENTION FACILITIES with LAND APPLICATION  
WASTEWATER BYPASS FORM

DEQ Facility ID: 5-30401 Facility Name: RW + SW #20 County: Pittsburg

Report all Total Retention Facility and  
Total Retention Facilities with Land Application  
wastewater bypasses to  
DEQ/ Environmental Complaints and Local Services  
within 24 hours at:

**1-800-522-0206**

Mail or Fax written report including copies of ANY test results  
within 5 days to:

Department of Environmental Quality  
Environmental Complaints and Local Services  
P.O. Box 1677  
Oklahoma City, OK 73101-1677  
Fax No. (405) 702-6226

DEQ notified:	<u>Sep</u>	<u>23</u>	<u>2018</u>	<u>1:14</u>	<input checked="" type="checkbox"/> AM	<input checked="" type="checkbox"/> PM	Received by:
Period of bypass:	From	<u>Sep</u>	<u>23</u>	<u>2018</u>	<u>8:05</u>	<input checked="" type="checkbox"/> AM	<input type="checkbox"/> PM
	To	<u>ON GOING</u>				<input type="checkbox"/> AM	<input type="checkbox"/> PM
Type of Bypass:	<input type="checkbox"/> Pipe	<input checked="" type="checkbox"/> Lagoon/Basin	<input type="checkbox"/> Manhole	<input type="checkbox"/> Head Works	<input type="checkbox"/> Lift Station	<input type="checkbox"/> Irrigation	
Strength of Bypass	<input type="checkbox"/> Raw	<input checked="" type="checkbox"/> Partially Treated	<input type="checkbox"/> Re-use (Category 4)				Amount of Bypass: <u>7,200</u> gpd
Type of samples taken:	<input type="checkbox"/> BOD	<input type="checkbox"/> TSS	<input type="checkbox"/> Fecal	<input type="checkbox"/> pH	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Other:	
Geographical location of bypass and receiving stream if appropriate:	<u>Lagoon #3 SW #20</u>						
Reason for bypass:	<u>Lagoon was close to bypassing</u>						
Steps taken to prevent recurrence:	<u>Repairs being made to sewer lines</u>						
Were fish or other wildlife affected as a result of the bypass?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No How?						
Impact to receiving stream and/or surrounding areas:	<u>None</u>						
Steps taken to clean up or treat bypass:	<u>bypass not complete</u>						
Reported by:	<u>Mark Watkins</u>			Title: <u>Contractor</u>			
Signature:	<u>Mark Watkins</u>			Date: <u>9/25/18</u> Phone #: <u>(918) 429-1686</u>			
DEQ E&P USE ONLY:							

Type of Contact:  Phone or  Site Visit Date: 10/08/18 Follow up Site Visit  Date: \_\_\_\_\_

Geographical location of bypass and receiving stream if appropriate: North of the third Lagoon cell into unname creek

Reason for bypass: Excessive rainfall and I&I issues in collections

Steps taken to prevent recurrence: Addressing I&I issues within collections, Under CO

**RECEIVED**

**SEP 26 2018**

Impact to receiving stream and/or surrounding areas: None

Steps taken to clean up or treat bypass: Pick up any litter/ solids and lime

Corrective action needed: \_\_\_\_\_

Comply by date: \_\_\_\_\_

**ECLS**

Reported information confirmed:  Yes  No If no, explain: \_\_\_\_\_

Comments: \_\_\_\_\_

Signature: Jameson M. Schulz  
ECLS Representative

ID #: 284572

Date: 10/08/18

OKC Central Office Use Only  
BYPASS ID #